Department of Mechanical Engineering

PVP 19

STATISTICAL QUALITY CONTROL

()								
Course Code	19ME4601D	Year	III	Semester	II			
Course Category	Program Elective-II	Branch	ME	Course Type	Theory			
Credits	3	L-T-P	3 - 0 - 0	Prerequisites	Nil			
Continuous Internal Evaluation	30	Semester End Evaluation	70	Total Marks	100			

Course Outcomes				
Upon	successful completion of the course, the student will be able to			
CO1	Familiarize students with some of Quality Basics and History	L2		
CO2	To discuss about Modeling Process Quality	L2		
CO3	Imparted knowledge about Statistical Quality Control	L4		
CO4	Awareness on basics of Control Charts for Attributes	L2		
CO5	Attain basic knowledge on Acceptance Sampling	L2		

Contribution of Course Outcomes towards achievement of Program Outcomes &														
Strength of correlations (H:High, M: Medium, L:Low)														
	PO1	PO2	PO3	PO4	PO5	PO6	PO7	PO8	PO9	PO10	PO11	PO12	PSO1	PSO2
CO1	1		1			2		2			3		1	3
CO2	1		1			2		2			3		1	3
CO3	1		1			2		2			3		1	3
CO4	1		1			2		2			3	3	1	3
CO5	1		1			2		2			3	3	1	3

Syllabus					
Unit No	Contents	Mapped CO			
I	QUALITY BASICS AND HISTORY: Meaning of quality, Factors effecting quality, Quality Principles, Quality function, Quality control, Aims and objectives of quality control, Characteristics, Cost of quality, Value of quality, Seven QC tools, Need of management of product quality, Historical perspective of quality control.	CO1			
II	MODELING PROCESS QUALITY: Variation: Stem-leaf Plot, Frequency distribution Histogram, Box Plot, Discrete Distributions Hyper geometric Distribution, Binomial distribution, Poison Distribution, Continuous Distributions- Normal, Gamma, Exponential and Weibull's distribution.	CO2			
III	STATISTICAL QUALITY CONTROL: Introduction, Concept of variability, Common vs. Special Causes, Types of Control charts, Measurement of control limits, Control charts for variables -large sample data, Warning limits, Revised control limits, Group control chart, Control chart with line trend.	CO3			
IV	CONTROL CHARTS FOR ATTRIBUTES: Control charts for non-confirming Models, control charts for fraction non-conforming. Process and Measurement System Capability Analysis: Using Probability plot, process	CO4			

Department of Mechanical Engineering

PVP 19

	capability ratios, specification limits and Tolerances.	
V	ACCEPTANCE SAMPLING: Introduction, Advantages and Disadvantages of Sampling methods, Sampling techniques, Sampling Risks and indices, Operating characteristic curves, Average outgoing quality Limit. Sampling plans Single, Double, Multiple and Sequential Sampling Plans Tightened Inspection, Dodge-Rooming system, Sequential plans.	CO5

Learning Recourse(s)

Text Book(s)

- 1. E. L. Grant Richard, R.S. Leavenworth, Design Statistical Quality Control, 7th Edition, McGrawHill Pvt Ltd New Delhi, 2011.
- 2. D. C. Montgomery, Statistical Quality Control,7th Edition, John Wiley Sons, 2012.

Reference Book(s)

- 1. M. Mahajan, Statistical Quality Control, Revised Edition, Dhanapat Rai & Co, 2007.
- 2. W.W.Hines, D. C.Montgomery, Probability and Statistics in Engineering and Management Science, John Wiley and Sons, New York, 1990.
- 3. Kapoor, V.K. and Gupta, S.P. (1978): Fundamentals of applied statistics, Sultan Chand & Sons. Gupta, R.C.(1974): Statistical Quality Control.

e-Resources & other digital material

1. https://nptel.ac.in/courses/116/102/116102019/